Knowledge Base Article



375 Field Communicator Li-Ion Power Modules May Fail If Exposed to RF Emitting Devices

Article ID:	NA-0900-0075		
Publish Date:	11 May 2010		
Article Status:	Approved		
Article Type:	General Product Technical Information		
Required Action:	Information Only		
User Discipline:	Operation		
Recent Article Revisi	on History:	Description of Revision	
11 May 2010		Update KBA that a return of affected failed Li-Ion Power Modules is not necessary.	
(See end of article for	or a complete revision his listing.)	story	
Affected Products:			
Product Line	Category	Device	Version
			1000

This Knowledge Base Article, **NA-0900-0075**, provides information regarding a potential situation that can result in the failure of the new Li-lon battery (Power Module) for the 375 Field Communicator.

It has been identified that the new Li-Ion Power Module for the 375 Field Communicator may fail if used, stored, or charged in close proximity to RF (Radio Frequency) emitting devices such as two way radios, walkie-talkies, etc.

More Information/Symptoms:

Should the Li-Ion battery (Power Module) be subjected to these types of RF emitting devices it is possible that the Li-Ion Power Module protection circuitry could activate to the level where the Li-Ion Power Module will fail as a result of a blown fuse in the protection circuitry.

The blown fuse failure of the protection circuitry will render the Li-Ion Power Module incapable of supplying power to the 375 Field Communicator except while connected to the charger.

The following specific criteria can be used to identify potentially affected Li-Ion Power Modules and the existence of failure due to the known condition.

1) Identification of Li-Ion Power Module

As there are 2 possible battery pack styles which have been made available for the 375 Field Communicator, it must first be confirmed the affected battery is the Li-lon type.

A Li-Ion Power Module(Battery Pack) can be identified by the tag on the underside or outside of the Power Module(Battery Pack) as shown below:



- 2) The Li-Ion Power Module is confirmed to be in the potentially affected revision level range.
 - Any Li-Ion Power Module at Rev K or earlier could be affected. Potentially affected Li-Ion Power Modules prior to Rev K will have no additional distinguishing markings other than being confirmed as a Li-Ion Power Module.



> Li-lon Power Modules at **Revision L, M**, or later are unaffected.



- 3) The affected Li-Ion Power Module is confirmed to exhibit the following behavior:
 - > 375 Field Communicator will not operate without charger

<AND>

> No LED's are illuminated on the battery pack when button is pressed and charger is not connected.

Confirming the Li-Ion Power Module is in the affected range and the presence of the 2 conditions under item **3**) above should confirm the situation reported in this KBA exists. However, the following behaviors related to the charger indicator lights may also be observed with this type of failure where a blown fuse in the Li-Ion Power Module has been encountered:

- Blinks yellow indefinitely when connected to pack
- Blinks green/yellow/green/yellow.... indefinitely when connected to pack
- Blink yellow for a few seconds then goes immediately to green (most common)

Work-around:

Avoid using, storing, or charging the 375 Field Communicator with the Li-Ion Power Module in close proximity to RF emitting devices.

Recovery Action:

To address this potential situation, the Li-Ion Power Module for the 375 Field Communicator has been updated with modifications to increase their immunity to sources of RF.

Should it be confirmed that an affected Li-Ion Power Module has failed due to the situation noted in this KBA, the following options exist:

1. Obtain a warranty replacement of the new updated Li-Ion Power Module with the improved RF immunity.

Note:

Affected Rev K or earlier Li-Ion Power modules confirmed as experiencing the failure mode described in this KBA will not need to be returned as it is a known situation relating to these affected Li-Ion Power Modules for which no failure analysis will be necessary.

The failed Li-Ion Power Modules should be recycled or disposed of as appropriate per the applicable local wastedisposal regulations.

2. For sites that may experience multiple failures of affected Li-Ion Power Modules, there are other 475 Field Communicator discount opportunities available.

Contact your local Emerson Sales channel for assistance with obtaining the appropriate replacement for the current situation.

Complete Article Revision History:		
Revision/Publish	Description of Revision	
11 May 2010	Update KBA that a return of affected failed Li-Ion Power Modules is not necessary.	
08 Feb 2010	General KBA updates and update for identfiying revisions of Li-Ion Power Module	

23 Oct 2009 Original release of article

©Emerson Process Management 2009. All rights reserved. For Emerson Process Management trademarks and service marks, <u>click this link to see</u> <u>trademarks</u>. All other marks are properties of their respective owners. The contents of this publication are presented for informational purposes only, and while every effort has been made to ensure their accuracy, they are not to be construed as warrantees or guarantees, express or implied, regarding the products or services described herein or their use or applicability. All sales are governed by our terms and conditions, which are available on request. We reserve the right to modify or improve the design or specification of such products at any time without notice.

View Emerson Products and Services: Click

This Link