



REVISIONS		
TR	ECO	DATE
A	8670	11-21-86
B	8701	2/86
C	8910	9/5/86



- NOTES**
- 1) SERIAL NO TAG (1 290) IS TO BE PLACED ON TOP OF COVER
 - 2) ALL PARTS SHOULD BE INSPECTED AND CAREFULLY CLEANED TO REMOVE ALL DIRT AND OTHER FOREIGN MATTER
 - 3) APPLY GREASE (6 150) LIBERALLY TO ALL COMPONENTS BEFORE ASSY
 - 4) INSPECT PER ES 6

- NOT SHOWN**
- 1 310 CLOSED POSITION TAG
 - 1 320 OPEN POSITION TAG
 - 2 160 PIPE PLUG
 - 2 170 BLEED VALVE
 - 3 110 PIPE PLUG
 - 3 120 BLEED VALVE
 - 6 150 GREASE
- 7 TUBING & FITTINGS

THIS DRAWING CONTAINS CONFIDENTIAL AND PROPRIETARY INFORMATION OF GIB BETTS AND IS SUBMITTED TO YOU FOR THE LIMITED PURPOSE OF PROVIDING YOU INFORMATION TO FACILITATE YOUR USE AND/OR MAINTENANCE OF PRODUCTS MANUFACTURED BY YOU FROM GIB BETTS. BY RECEIVING THIS DOCUMENT YOU AGREE NOT TO DISCLOSE CONFIDENTIAL INFORMATION FOR ANY PURPOSE OTHER THAN THE LIMITED PURPOSE STATED HEREIN AND FURTHER AGREE NOT TO DISCLOSE SUCH INFORMATION TO OTHERS EXCEPT IN ACCORDANCE WITH THE LIMITED PURPOSE STATED HEREIN.	GENERAL TOLERANCES UNLESS OTHERWISE SPECIFIED: DECIMAL .1K .3MM ANGULAR .5 CONCENTRICITY .008 .27 FILLETS .03R 794R	DWN JIM JONES 10/11 CHK RGS 11/25/85 APP D ALL 11/25/85 APP D	TITLE ASSEMBLY DRWG TR10210-M4 ACTUATOR	
	SURFACE FINISH REMOVE BURRS AND SHARP EDGES <input checked="" type="checkbox"/> DO NOT SCALE DWG	S O No L O No	PART No 65270	
	SCALE NONE DWG SIZE D	SHEET 1 OF 1	REV C	